



2006 MERCEDES E350W4 - PLT BLU

VIN: WDBUF87J56X198585 Work Order #: 1965619
MANHEIM AUTO AUCTION

VIN: WDBUF87J56X198585
Body Style: 4DSN - Sun Roof
Ext Color/Code: PLT BLU - 353
Int Color/Code: BEI - 135
Mileage: 32,168
ECM Mileage:
Seller: MERCEDES-BENZ FINANCIAL
Title State: NJ
Certified: No
Condition/Grade: 4.0, Above Average
Sale: 11
Lane: 19
Run: 110
Inspection: JHEVNER 01/29/2009
Drivable: Yes
In Service Date: 12/19/2005



VEHICLE INFORMATION

MECHANICAL

6 Cylinder Gas
 Automatic
 AWD
 Pwr Brakes
 3.5 L

FLUID LEVELS

Fuel Level: 1/2

TIRES AND WHEELS

Tire	Tread Depth	Brand	Size
Left Front:	7/32"	CONTINENTAL	245/45R17
Left Rear:	7/32"	CONTINENTAL	245/45R17
Right Front:	6/32"	CONTINENTAL	245/45R17
Right Rear:	7/32"	CONTINENTAL	245/45R17
Spare:	0/32"		

Tire Condition: Average
Wheels: Alloy

INTERIOR OPTIONS

Average	Pwr Lock	Pwr Steering
BEI - Textile	Pwr Window	Pwr Seats - Both
Int Odor: OK	A/C	Cruise Ctl
Wood Trim	Rear Defrost	CD Player
Dash	Side Air Bags	Dual Air Bags
	Power Mirrors	Heated Mirrors
	ABS Brakes	CD Changer
	Premium Stereo - OE	4 Door
	Fog Lamps	Maintenance Records
	Trip Counter	CD Changer - OE - 6.00
	Power Trunk/Liftgate	Trip Computer
	Heated Seats - Front	Keyless Entry
	On-Board Computer	Floor Mats
	Satellite Radio	Security System
	Steering Wheel Audio Control	Navigation System
	Traction Control	Dual Air Conditioning
	HomeLink	Satellite Radio
	Heated Seats	Memory Seat
	Woodgrain Interior Package	Power Telescopic Steering
	Power Tilt Steering	Turn Signal Mirrors
	Navigation System	Rain Sensor Windshield
	Directional Stability Control	Sunshade - Power

KEYS

Master Key - 1

ANNOUNCED CONDITION:

INTERNET REMARKS:

REMARKS/ADDITIONAL DAMAGE: Books, Previous Paintwork

DISCLOSURES:

REMARKS:

2006 MERCEDES E350W4 - PLT BLU

VIN: WDBUF87J56X198585 Work Order #: 1965619

MANHEIM AUTO AUCTION**DAMAGES**

DESCRIPTION	CONDITION	SEVERITY	REPAIR HOURS	PAINT HOURS	PART HOURS	TOTAL HOURS
LF Fender	Prev Repair 6.5	Acceptable	.00	.00	.00	.00
LF Tire	Slight Wear	None	.00	.00	.00	.00
LF Door	Prev Repair 6.5	Acceptable	.00	.00	.00	.00
LR Tire	Slight Wear	None	.00	.00	.00	.00
RF Fender	Prev Repair 6.0	Acceptable	.00	.00	.00	.00
RF Tire	Slight Wear	None	.00	.00	.00	.00
RF Door	Prev Repair 7.0	Acceptable	.00	.00	.00	.00
RR Door	Prev Repair 6.5	Acceptable	.00	.00	.00	.00
R Qtr Panel	Prev Repair 6.0	Acceptable	.00	.00	.00	.00
RR Tire	Slight Wear	None	.00	.00	.00	.00
TOTALS			.00	.00	.00	.00

REPAIRED

DESCRIPTION	CONDITION	SEVERITY	REPAIR HOURS	PAINT HOURS	PART HOURS	TOTAL HOURS
LF Wheel	Scratched	4" to 5"	.00	.00	.00	.00
LR Wheel	Mult Scratches	GR 12"	.00	.00	.00	.00
RF Wheel	Scraped	GR 12"	.00	.00	.00	.00
RR Wheel	Scraped	GR 12"	.00	.00	.00	.00
TOTALS			.00	.00	.00	.00